HABS No. NY-6054

Roslyn Presbyterian Church 33 East Broadway Roslyn Nassau County New York

HATE. NY, 40-ROS

## PHOTOGRAPHS WRITTEN HISTORICAL AND DESCRIPTIVE DATA REDUCED COPIES OF MEASURED DRAWINGS

Historic American Buildings Survey National Park Service Department of the Interior Washington, D.C. 20240 Form 10-920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HARSS NY 30-ROS

## ARCHITECTURAL DATA FORM

STATE NEW YORK	COUNTY	SSAU	TOWN OR VICINI ROSLYN	
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) ROSLYN PRESBYTERIAN CHURCH				HABS NO. NY-6054
SECONDARY OR COMMON NAMES OF STRUCTURE				
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)  33 East Broadway				
DATE OF CONSTRUCTION (INCLUDE SOURCE) 1851-1852		ARCHITECT(S) (INCLUDE SOURCE)		
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE)  The only surviving church of two churches built in Roslyn before 1852.				
STYLE(IF APPROPRIATE) Spare Greek Revival				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)  Frame on stone rubble foundation				
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)  One story with gallery, 2 bays wide, 3 bays deep, rectangular with addition, 35'x52'.  For floor plans see HABS measured drawings.  EXTERIOR FEATURES OF NOTE				
Broad gable roof, enclosed hipped roof porch across west front, molded cornice with frieze which returns along the gable ends. The tower no longer exists (old photographs show a three-section tower: all sections square with molded cornice).				
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) The church had a two aisle plan with side pews abutting the north and south walls. The 1870 partition is used as a kitchen and vestibule. The original nave is one large room rising the full height of the church. The west gallery is reached by an open stairway. The new (1972) gallery (cont'd p. 2).				
MAJOR ALTERATIONS AND ADDITIONS WITH DATES  1870 Hipped roor porch added. Partition now used as kitchen and vestibule.  1930 Steeple removed. The fluted cast-iron columns which supported the gallery removed.  1972 New gallery built. Interior chimneys at rear removed.				
PRESENT CONDITION AND USE Present Owners: Mr. & Mrs. Richard D. Ponemon, building used as residence.				
OTHERINFORMATION AS APPROPRIATE Church faces west and was built on a lot 60'x100', graded before the church was built. William Cullen Bryant was a trustee of the church.				
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Bryant Library, Rosyln. Local History Collection. Rosebrock, Gerry & Roger & Peggy & Ellen. Roslyn Landmark Society Annual House Tour Guide. 1973. pp. 27-35.				
COMPILER, AFFILIATION Eleni Si by the Rosebrocks (May 1974)		ian, HABS, from	reports DA	TE 4/13/84

## INTERIOR FEATURES OF NOTE (CONT'D):

forms a hallway on the east. The choir stairway, which reverses on itself before reaching the gallery floor, is sheathed with plain vertical boarding. The newel is San Domingo mahogany. The original floor was yellow pine. There is a dado about 5' high on three walls of the ground floor. During the 1972 repovation of the church, the dado in the closet beneath the gallery stair was found to have been grained. In this section the wall above the dado was papered with a wallpaper in grisaille.

The hall windows have small wooden leaf-shaped latches. Similar fish-tail latches lock the gallery windows into an open position.